



TURCO[®] 6088A

ENVIRONMENTALLY COMPATIBLE PAINT REMOVER

DESCRIPTION:

TURCO 6088A is a thixotropic, blue, liquid paint remover developed for stripping resistant finishes such as epoxies, epoxy primers, polyurethanes, alkyds and similar catalyzed paints.

TURCO 6088A paint remover offers a significant advance in improving work place safety since it does not generate obnoxious fumes or odors and is free from methylene chloride, chlorinated solvents, phenols, chromates, volatile acids, ammonia and amines.

TURCO 6088A can be used on aluminum, mild steel, cast iron, cadmium plated steel and titanium when used as directed. TURCO 6088A is not recommended for use on high strength steel or magnesium.

FEATURES:

TURCO 6088A offers these features:

1. Contains no HAP's
2. Flash point over 95°C, Pensky Martens
3. Freely rinses from surfaces with high volume, high pressure cold water
4. Clings to vertical and overhead surfaces
5. Free from obnoxious fumes and odors
6. Used at ambient temperature, above 15°C

USE INSTRUCTIONS:

Application: Apply a thick, uniform coating to surface being stripped by means of non-atomizing spray or by brushing. Allow sufficient time for stripper to work. Agitation with a stiff bristle brush will aid in removal of finish. Do not use on Plexiglas and other similar thermosetting materials.

Rinsing: Rinse with high volume, high pressure cold water or steam.

DISPOSAL INFORMATION:

Dispose of spent remover and paint residue per local, state and regional regulations. Refer to TURCO MATERIAL SAFETY DATA SHEET for additional disposal information.

CAUTION!

TURCO 6088A contains hydroxyacetic acid. Avoid contact with eyes, skin and clothing. Do not take internally. Use with adequate (equivalent to outdoor) ventilation. Do not spray in confined areas. Avoid prolonged breathing of vapors.

Protective clothing, such as a chemical face shield or goggles, gloves, boots and apron made from solvent resistant materials should be worn and a NIOSH-approved respirator equipped with mechanical filter should be worn for mist conditions.

Store containers at a temperature between 0° to 50°C.

Before using this product refer to container label and TURCO MATERIAL SAFETY DATA SHEET for additional precautionary, handling and first aid information.

NOTICE:

The above information and recommendations concerning this product are based upon our laboratory tests and field use experience with this or similar products. However, since conditions of actual use are beyond our control, any recommendations or suggestions are made without warranty, express or implied. Manufacturer's and seller's sole obligation shall be to replace that portion of the product shown to be defective. Neither shall be liable for any loss, damage, or injury, direct or consequential, arising out of the use of this product.

Rev.9/99(Sup. 11/86)
TDB #452